



Designación	M kg/m	P kN/m	h mm	b mm	t _w mm	t _f mm
HEA 100	16,7	0,167	96	100	5,0	8,0
HEA 120	19,9	0,199	114	120	5,0	8,0
HEA 140	24,7	0,247	133	140	5,5	8,5
HEA 160	30,4	0,304	152	160	6,0	9,0
HEA 180	35,5	0,355	171	180	6,0	9,5
HEA 200	42,3	0,423	190	200	6,5	10,0
HEA 220	50,5	0,505	210	220	7,0	11,0
HEA 240	60,3	0,603	230	240	7,5	12,0
HEA 260	68,2	0,682	250	260	7,5	12,5
HEA 280	76,4	0,764	270	280	8,0	13,0
HEA 300	88,3	0,883	290	300	8,5	14,0
HEA 320	97,6	0,976	310	300	9,0	15,5
HEA 340	104,8	1,048	330	300	9,5	16,5
HEA 360	112,1	1,121	350	300	10,0	17,5
HEA 400	124,8	1,248	390	300	11,0	19,0
HEA 450	139,8	1,398	440	300	11,5	21,0
HEA 500	155,1	1,551	490	300	12,0	23,0
HEA 550	166,2	1,662	540	300	12,5	24,0
HEA 600	177,8	1,778	590	300	13,0	25,0